



CSA INTERNATIONAL

# FACTORY INSPECTION REPORT

Factory ID: 工廠代碼 4550566 Trip Number: 檢驗代碼 R409 Page 1 of 1  
 Factory Contract: 工廠合約碼 233619 PO Number: 帳單號碼 \_\_\_\_\_  
 Master Contract: 主合約碼 173314 Arrival: \_\_\_\_\_ Depart \_\_\_\_\_ Date: 2009-01-  
 Legacy Number(s): 檔案號碼 LR 54479 抵達時間 14:15 離開時間: 16:00 日期 07  
 Summary Inspection Code(s): 綜合檢驗代碼 K

Submitter: 4549924 申請者	Factory: Magic Power Technology Co. Ltd. 工廠 9F-6 No. 268 Lien Cheng Rd. Chung-Ho City Taipei, TAIWAN
Is a system in place for recording customer complaints? 是否具備客戶抱怨記錄系統? Yes	Have any complaints been received since last inspection? 自最近一次檢驗至今是否曾發生任何客戶抱怨? No
Traceability of Incoming Materials/Procedures Reviewed & Found Acceptable? 進料追溯性/程序審核結果之符合性? Yes	

**Observations 觀察紀錄:**  
**Factory:** Reviewed the contact information and "Factory Contact Questionnaire" with no changes. Manufacturer is registered to ISO 9001:2000 by URS. Reviewed the system and record of customer complaints, no safety related issues were found since last inspection. Manufacturer declared that they did not initiate any safety related recall activities or be contacted by CPSC, ESA, or any other regulatory body about safety related product incidents or defects since last inspection. Reviewed calibration record of test equipment, found that the calibration is traceable to national standard. Observed the operation in receiving inspection, in-process quality control, final inspection, treatment of non-conforming product and management of storage & shipping, found that they are all follow the manufacturer's procedure and instruction. Manufacturer was producing non-CSA marked power supplies at time of inspection.  
**Class 5311: POWER SUPPLIES- Component Type, Model SPS 1063, (Standards Referenced): C22.2 No. 0, 0.4, 60950, UL 60950. (Reports Referenced): 1223973 (Marking):** CSA monogram, C/US, Model designation, Submitter's name, Complete electrical rating, Serial number appear accepted adhesive label attached to enclosure. One CSA-C/US Marked sample was drawn from current stock for inspection on construction and components against Certification Report with compliance results. Manufacturer declared that 977 pcs of certified power supplies have been produced in the period of October 2008 to December 2008.

Factory Tests Applied: 工廠測試

Class No. 產品分類	Type of test: 測試項目	Manufacturer: 製造商	Model: 形式	S/N or ID 序號或識別碼	Cal Due Date 校正期限	Value: 數值	% of Prod 執行比率	Funct. Check 功能查核	Acceptable 符合
5311	Hi-Pot test	GW instek	GPI-745A	IDEE 133983	Oct. 2009	1500V ac	100	Yes	Yes
5311	Earthing-Continuity test	GW instek	GPI-745A	IDEE 133983	Oct. 2009	0.1 Ω Max./25A	100	Yes	Yes

Immediate changes required as a condition of continued certification 為維持符合驗證,須立即採行之變更:  
 Class 5311: None

Class No. 產品分類	Inspection Codes 檢驗代碼	Marketing Code	Is construction and material in compliance with reports? 是否符合驗證報告	Is the mfg aware of the new effective dates? 工廠是否了解最新之生效日期?	Are new requirements complied with? 新要求是否符合?	Is marking in accordance with report? 標誌是否符合驗證報告?	How Applied? 如何標示	Was the CSA Mark removed? 是否已移除標誌?	were defects corrected on all samples? 缺點是否已改正?	Retest/Component Samples selected? 產品/零件是否抽樣?	Time Spent Per Class (hrs:min)	Follow Up Reviewed & Resolved? 審核與解決追蹤事項?	Follow Up Required? 有追蹤?
Factory	—	—	—	—	—	—	—	—	—	—	00:30	—	—
5311	K	R	Yes	No	N/A	Yes	Label	N/A	N/A	N/A	01:15	N/A	No

As the facility representative, the undersigned, hereby agrees that all production subsequent to the time of the inspection will incorporate required changes.  
 工廠代表簽署如下並同意此後所有生產均符合所要求之變更。  
 Name: 姓名 Ms. Chen Li-Li 陳立利 Name: 姓名 Jason Lu CSA Office: CC55T  
 (Facility Representative) 工廠代表 (CSA Representative) CSA 代表  
 Signature: 簽名 陳立利 Signature: 簽名 Jason Lu Employee No: GTS-47